

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3861	DATE	July 21 , 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to improper design of an out handle at side doors, the sliding part of the handle expands by absorbing moisture, interferes to a handle case when pulling the out handle and it does not return to the initial condition. Therefore door does not lock securely, it could open during driving in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-FF21S	IGNIS	2016	15,437
		TOTAL	15,437