

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3864	DATE	Jul. 22. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty buses, due to the improper tightening work of front brake hoses, there are some that the tightening torque of the nuts at the hose connecting parts is insufficient. Therefore, if it is continued to be used under the condition, the nuts at the hose connecting parts may be loosen, causing the brake air to leak, resulting the braking force to decline in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QTG-RU1ASCA	[HINO SELEGA]	2016	81
QRG-RU1ESBA		2016	52
LDG-RU8JHBA		2016	16
SDG-RU8JHBA			
		TOTAL	149