

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3865	DATE	July 22 ,2016
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>On certain heavy duty buses, due to the improper tightening work of front brake hoses, there are some that the tightening torque of the nuts at the hose connecting parts is insufficient. Therefore, if it is continued to be used under the condition, the nuts at the hose connecting parts may be loosen, causing the brake air to leak, resulting the braking force to decline in the worst case.</p>	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QTG-RU1ASCJ	[ISUZU GALA]	2016	60
QRG-RU1ESBJ		2016	27
LDG-RU8JHBJ SDG-RU8JHBJ		2016	15
		TOTAL	102