VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3871	DATE	July 21,2016
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Improperly coated at the end cap section, the outer pipe of the gas-filled back door stay may corrode by influence of salt air in coastal districts. If a vehicle with this condition is used continuously, it may happen that corrosion progresses, the outer pipe swells, the end cap breaks, and then the outer pipe fractures when the back door is opened. In the worst case, people being around the back door may be injured consequently.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-L375S	TANTO	2007-2013	693,683
DBA-L375S			
CBA-L385S			104,867
DBA-L385S			
	•	TOTAL	798,550