

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3875	DATE	August 3,2016
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p><1> The exhaust pipe of the shovel loader may lack strength because of improper design. Accordingly, if the shovel loader is used as it is, its exhaust pipe resonates with engine vibration and may crack, and exhaust gas leaks in the worst case.</p> <p><2> The engine vibration of the shovel loader is transmitted to the starting motor through the electric wiring because of improper wiring directions, and it may distort and deform the resin cover of the starting motor magnet. As a result, the resin cover may crack or have clearance. If the starting motor is used as it is, water may enter through the damaged portion and rust the inside. The starting motor becomes unable to start the engine in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-WA120	「WA470-7」	2012 - 2016	46
		TOTAL	46