

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3878	DATE	August 24,2016
MANUFACTURER	TOHO CAR CORPORATION		
DESCRIPTION OF DEFECT	In the U-bolts of the trailer, for the production of U-bolts is inappropriate, there are things that strength is insufficient. Therefore, continuing to use as is, U-bolts are broken due to vibration or the like during running, in the worst case, the axle can not be maintained, it may become impossible to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TC29F9C2S	-	2016	7
TC36F6C3S	-	2016	4
TC36H1C33	TOHO TC36H1C33	2016	1
TC36H1C34	TOHO TC36H1C34	2016	1
TD28H9E2S	-	2016	1
TE28H8C21	TOHO TE28H8C21	2016	1
TE36H2C3	TOHO TE36H2C3	2016	5
TE36J3E3S	-	2016	1
TF2523	TOHO TF2523	2016	1
TF36H2C3	TOHO TF36H2C3	2016	8
TF50H4C3	TOHO TF50H4C3	2016	1
TL26G4E2	TOHO TL26G4E2	2016	1
TL26H9E2S	-	2016	1
TL32F4E3S	-	2016	1
TL35G1E3S	-	2016	1
TL43J3E3S	-	2016	1
TOTAL			36