## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3879	DATE	August 4,2016	
MANUFACTURER	MITSUBISHI MOTORS CORPORATION			
DESCRIPTION OF DEFECT	In the door latch for right side door, the lock mechanism may no operate properly when the temperature become high due to insufficient precision of the part caused by inappropriate manufacturing process of the component parts. As a result, the door may not be locked securely and, in the worst case, the door may open while driving.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-B11W	$\lceil_{\mathbf{eK}} floor$	2015~2016	11,107
DBA-B11A	「eK SPACE」	2015~2016	3,841
DBA-B21W	$\lceil \mathrm{DAYZ}  floor$	2015~2016	32,667
DBA-B21A	「DAYZ ROOX」	2015~2016	31,886
		TOTAL	79,501