

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3882	DATE	August 31.2016
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	<p>① Steering device on agricultural tractor was designed with improper stopper for snap ring of hydraulic cylinder cap, which can cause snap ring to disengage. Operation under this condition may lead to oil leakage and might result in steering and traveling unable.</p> <p>② Steering device on agricultural tractor was designed with improper hydraulic cylinder cap, which can cause excessive stress on snap ring of the cap. Operation under this condition may lead to the detent breakage and oil leakage, and might result in steering and traveling unable.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「YT463」	2015—2016	178	
	「YT470」	2015—2016	240	
	「YT490」	2015—2016	301	
			TOTAL	720