

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3884	DATE	26 Aug 2016
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	The rubber O ring between cooling water pipe and engine cylinder may be not installed properly during assembly process. It may cause much cooling water leakage and may result in overheat in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
EBL-ZRT20D	ZRX1200 DAEG	2016	1335	
		TOTAL	1335	