

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3895	DATE	September 23,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate material for the internal electric junction in the alarming horn, improper conduction may occur due to oxide coating generated by repetitive water intrusion at the internal electric junction. As a result, the alarming horn may not honk.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-U61V	「MINICAB」	2011～2013	965
GBD-U61V		2011～2013	21,602
EBD-U62V		2011～2013	1,269
GBD-U62V		2011～2013	12,870
GBD-U61T GBD-U61TP		2011～2014	10,429
GBD-U62T		2011～2013	21,124
ZAB-U67V	「MINICAB -MiEV」	2011～2012	4,833
ZAB-U68V		2013～2015	1,242
ZAB-U68T		2013～2015	915
EBD-U71V	「CLIPPER」	2012～2013	1,693
GBD-U71V		2012～2013	30,237
EBD-U72V		2012～2013	865
GBD-U72V		2012～2013	10,145
GBD-U71T GBD-U71TP		2012～2013	7,293
GBD-U72T		2012～2013	8,488
		TOTAL	133,970