VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	3896	DATE	September 30, 2016		
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD				
DESCRIPTION OF	With regard to a direction indicator and/or a side marker lamp				
DEFECT	which are equipped on a wheel crane, our workman instructions				
	were inappropriate. So when it installed bulbs what were				
	removed at painting process, there was a vehicle which the				
	wrong bulbs were installed.				
	Therefore, it would be insufficient of the brightness of the				
	direction indicator. And it would be not satisfied with Paragraph				
	(2) of Article 41 of the Safety Standard.				

TYPE	COMMERCIAL	MODEL YEAR		NUMBER OF
TIPE	NAME	RECALLED		VEHICLE
UDS-EG04	RK700-2	2015-2016		10 units
			TOTAL	10