

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3899	DATE	September 29 ,2016
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In some engine control units fitted in light- and medium-duty trucks, a section to which the vent plug for ventilation attached could, as improperly coated, corrode from exposure to water, undermining its water-proof, thereby allowing water entry into the unit. As a result, the water in the unit may cause short circuit, which then may turn on the warning lamp and diminish power. In the worst case, the vehicle could be immobilized after engine stall while running.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FRR90T2 TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2	[FORWARD]	2013-2015	37,098
SDG-FRS90S1 SDG-FRS90S2 SKG-FRS90S2 TKG-FRS90S2		2013-2015	178
SKG-FSR90S2 SKG-FSR90T2 SPG-FSR90S2 SPG-FSR90T2		2013-2015	2,495
SDG-FSS90S1 SDG-FSS90S2 SKG-FSS90S2 SPG-FSS90S2		2013-2015	199
LKG-FTR90S2 LKG-FTR90T2 LPG-FTR90S2 LPG-FTR90T2		2013-2015	2,581
SDG-GSR90S2		2013-2014	34
TKG-NHR85A TKG-NHR85AN		[ELF]	2013-2015
TKG-NJR85A TKG-NJR85AD TKG-NJR85AN TKG-NJR85N TQG-NJR85AN	2013-2015		14,274

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TKG-NKR85A TKG-NKR85AD TKG-NKR85AN TKG-NKR85AR TKG-NKR85N TKG-NKR85R	[ELF]	2013-2014	13,138	
SKG-NKR85YN		2013-2014	1,444	
TKG-NLR85AN TKG-NLR85AR TKG-NLR85N TQG-NLR85AN		2013-2014	5,370	
TKG-NLS85AN		2013-2014	70	
TDG-NMR85AN TKG-NMR85AN TKG-NMR85AR TKG-NMR85N TKG-NMR85R TQG-NMR85AN TQG-NMR85N		2013-2015	6,420	
TDG-NMS85AN		2013-2014	270	
TKG-NNR85AN TKG-NNR85AR		2013-2014	628	
TKG-NNS85AR		2013-2014	61	
TKG-NPR85AN TKG-NPR85AR TQG-NPR85AN		2013-2015	12,529	
SKG-NPR85YN		2013-2014	4,175	
SKG-NPS85AN SKG-NPS85AR TDG-NPS85AN TDG-NPS85AR		2013-2014	996	
TKG-BJR85A TKG-BJR85AD TKG-BJR85AN		[CONDOR]	2013-2014	50
TKG-BKR85A TKG-BKR85AD TKG-BKR85AN TKG-BKR85AR TKG-BKR85N TKG-BKR85R			2013-2014	79
SKG-BKR85YN	2013-2014		8	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-BLR85AN TKG-BLR85AR TKG-BLR85N	[CONDOR]	2013-2014	43
TKG-BMR85AN TKG-BMR85AR TKG-BMR85N TKG-BMR85R		2013-2014	76
TKG-BNR85AR		2014	3
TKG-BNS85AR		2013-2014	4
TKG-BPR85AN TKG-BPR85AR		2013-2014	112
SKG-BPR85YN		2013-2014	61
TDG-BPS85AN TDG-BPS85AR		2013-2014	25
TKG-LHR85A TKG-LHR85AN		[TITAN]	2013-2014
TKG-LJR85A TKG-LJR85AD TKG-LJR85AN TKG-LJR85N	2013-2014		747
TKG-LKR85A TKG-LKR85AD TKG-LKR85AN TKG-LKR85AR TKG-LKR85N TKG-LKR85R	2013-2014		522
SKG-LKR85YN	2013-2014		3
TKG-LLR85AN TKG-LLR85AR TKG-LLR85N	2013-2014		196
TKG-LMR85AN TKG-LMR85AR TKG-LMR85N TKG-LMR85R	2013-2014		201
TKG-LNR85AN TKG-LNR85AR	2013-2014		109
TKG-LNS85AR	2014		3
TKG-LPR85AN TKG-LPR85AR	2013-2014		458
SKG-LPR85YN	2013-2014		101

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TDG-LPS85AN TDG-LPS85AR	[TITAN]	2013-2014	26
		TOTAL	110,256

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FRR90S1 SKG-FRR90S2 SKG-FRR90T2 TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2	[FORWARD]	2010-2015	140
SDG-FRS90S1		2012	1
SKG-FSR90S2 SKG-FSR90T2		2011-2012	6
LKG-FTR90S2 LKG-FTR90T2		2010-2013	17
SKG-NHR85A TKG-NHR85A TKG-NHR85AN	[ELF]	2011-2012	7
SKG-NJR85A SKG-NJR85AD SKG-NJR85AN TKG-NJR85A TKG-NJR85AD TKG-NJR85AN		2011-2013	27
SKG-NKR85AD SKG-NKR85AN SKG-NKR85R TKG-NKR85A TKG-NKR85AD TKG-NKR85AN TKG-NKR85AR TKG-NKR85N		2011-2013	24
SKG-NKR85YN		2011-2012	6
SKG-NLR85AN TKG-NLR85AN		2011-2012	8
SDG-NMR85AN SKG-NMR85AN SKG-NMR85N SKG-NMR85R TKG-NMR85AN TKG-NMR85N TKG-NMR85R		2011-2013	23

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TDG-NMS85AN	[ELF]	2012	2	
TKG-NNR85AR		2012	2	
SKG-NPR85AN SKG-NPR85AR TKG-NPR85AN TKG-NPR85AR TQG-NPR85AN		2011-2013	96	
SKG-NPR85YN		2011-2012	19	
SDG-NPS85AN TDG-NPS85AN TDG-NPS85AR		2011-2013	11	
SKG-AJR85AD		[ATLAS]	2011	1
SKG-AKR85A TKG-AKR85R			2011-2012	2
TKG-ALR85AN	2012		1	
SKG-AMR85AN SKG-AMR85R TKG-AMR85AN	2011-2012		3	
TKG-APR85AN	2012		2	
SDG-APS85AN	2011		1	
TKG-BKR85N	[CONDOR]		2013	1
TKG-BPR85AR		2011	1	
		TOTAL	401	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Engine Control Unit	8-98184577-4	2013	3
	8-98198600-2	2014	1
	8-98214504-0	2013	10
	8-98214506-0	2013	2
	8-98276043-0	2014-2015	17
	8-98276045-0	2014-2016	12
	8-98276053-0	2014-2015	3
	8-98276055-0	2014	2
	8-98276060-0	2015	1
	8-98276061-0	2014-2015	12
	8-98276062-0	2014-2015	5
	8-98277656-0	2014	1
	8-98277674-0	2016	1
		TOTAL	70