

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 8 8 7	DATE	Sep.15.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the engine cooling system, due to an insufficient strength, the lever at the water pump cooling channel control valve may break. Then the piston to switch control valve comes out causing engine coolant leak. If the vehicle continues to be driven in this condition, in the extreme cases, it becomes to engine overheating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-ZV37	SKYLINE	2014	1,330
DBA-YV37		~ 2015	150
		TOTAL	1,480