

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3877	DATE	September 1, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the gas charging type of liftgate stay damper, due to the inappropriate coating of outer tube at the end-cap, the stay damper may corrode by salt at the salt damage region. Therefore, continued to use under the condition, the corrosion advances and outer tube swells and the end cap may crack. In the worst case, when opening the lift gate, the outer tube may break off, resulting in injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BL3FW	Mazda「Axela」	2009-2013	2,444
DBA-BL5FW		2009-2013	32,685
DBA-BLEAW		2009-2013	857
DBA-BLEFW		2009-2011	14,789
DBA-BLFFW		2011-2013	11,266
CBA-GH5AW	Mazda「Atenza」	2008-2012	1,152
DBA-GH5FW		2007-2012	7,242
DBA-GHEFW		2007-2012	4,813
CBA-GH5AS		2008-2012	497
DBA-GH5FS		2007-2012	7,141
DBA-GHEFS		2007-2009	556
LDA-GJ2AW		2014-2015	1,781
LDA-GJ2FW		2012-2015	17,487
DBA-GJ5FW		2012-2015	2,214
DBA-GJEFW		2012-2015	3,632
LDA-DK5AW	Mazda「CX-3」	2014-2015	9,354
LDA-DK5FW		2014-2015	22,677
LDA-KE2AW	Mazda「CX-5」	2012-2015	44,679
LDA-KE2FW		2012-2015	56,736
DBA-KE5AW		2013-2015	2,643
DBA-KE5FW		2013-2015	1,798

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-KEEAW	Mazda「CX-5」	2012-2013	3,310
DBA-KEEFW		2012-2015	21,490
DBA-CWEAW	Mazda「Premacy」	2010-2015	3,473
DBA-CWEFW		2010-2014	48,748
DBA-CWFFW		2012-2015	33,096
DBA-CWEAWN	Nissan「Lafesta」	2011-2015	2,509
DBA-CWEFWN		2011-2014	25,288
DBA-CWFFWN		2013-2015	10,584
		Total	394,941