

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3892	DATE	Sep.14.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger air bag inflator of the subject vehicles, due to improper welding of the high pressure gas sealing disk, there is a possibility that the opening pressure of the sealing disk could be reduced. In this condition, the compressed gas could escape from the inflator causing the air bag to inflate spontaneously.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AGL20W	[RX200t]	2015-2016	108
DBA-AGL25W			190
DAA-GYL20W	[RX450h]	2015-2016	210
DAA-GYL25W			766
		TOTAL	1,274