

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3890	DATE	September 15, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the vehicles equipped with the adaptive LED head light, due to incorrect initial adjustment of the optical axis, the optical axis may be adjusted in condition that the axis is deviated to the left. Therefore, the head light beam direction may not meet the safety standard section 32.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM5AP	Mazda「Axela」	2016	108
DBA-BM5AS		2016	2
DBA-BM5FP		2016	373
DBA-BM5FS		2016	38
LDA-BMLFS		2016	1,152
DAA-BYEFP		2016	88
		Total	