

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2366	DATE	Oct. 3 rd 2016
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate controlling of the manufacturing process, the welding of the pipe for the propeller shaft might not be robust enough. Thus, crack may be displayed on the joint part between the pipe and propeller shaft. When keep driving under such situation, crack may progress. This may lead to a breakage of the joint parts of the propeller shaft, which results in loss of propulsion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FV44M	BMW M5	2014	48
ABA-LZ44M	BMW M6 Cabriolet	2014	2
	BMW M6 Coupe	2014	7
ABA-6C44M	BMW M6 Gran Coupe	2014	14
		TOTAL	71