## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2387	DATE	Oct, 31, 2016
MANUFACTURER	DUCATI MOTOR HOLDING SpA		
	(Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	Due to an error in the size of the slots on rear wheel rim hub, it is		
	necessary to check for proper installation of the rear wheel rim on		
	wheel shaft. Indeed, it is possible that the rear wheel rim might		
	have been installed in the wrong way, with the 4 rear wheel shaft		
	driving pins inserted in the slots rather than in the 4 relevant		
	holes. Should this be the case, you might find a noisy rear wheel		
	and under extreme situations, a loss of traction of the vehicle		
	during use.		
	Authorized Ducati dealers will check the rear wheel and the driving pins. If there is damage, replace the rear wheel and the pins. If there is no damage, installing these error-proof inserts will avoid any chance of wrong installation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-GA01	XDiavel S	2016	138
		TOTAL	138