

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 9 0 8	DATE	O c t . 2 5 . 2 0 1 6
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate manufacturing of oil seals of the clutch push lever in the power transmission device, micro cracks were found in some of the said oil seals. If the clutch is operated continuously, the cracks may develop due to the hydraulic pressure inside the engine while running and that may cause the engine oil to leak.</p> <p>In the worst case scenario, the vehicle may collapse caused by the leaked oil adhering onto the rear tire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B K - D G 1 5 J	W R 2 5 0 R	2 0 1 4 ~ 2 0 1 6	1 , 6 8 5
	W R 2 5 0 X		1 , 3 8 4
		TOTAL	3 , 0 6 9