VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3914	DATE	October 28 ,2016
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy duty buses, due to improper quenching of the brake expander wedge, there are some the hardness is insufficient. Therefore, a wedge may be worn out by the repeated braking, causing a braking force to change, resulting the wedge to be damaged and the braking force of the wheel unable to work in the worst case.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QTG-RU1ASCJ	[ISUZU GALA]	2016	24
QRG-RU1ESBJ		2016	7
LDG-RU8JHBJ SDG-RU8JHBJ		2016	4
		TOTAL	35

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Expander	5-86534835-0	2016	5
	5-86542751-0	2016	121
		TOTAL	126