

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2389	DATE	2016/11/16
MANUFACTURE	FENDT (Japanese Importer :MSK Farm Machinery Corporation CEO Toshiki Sugino )		
DESCRIPTION OF DEFECT	The noise insulator (absorbing noise in the hydraulic system) may have a crack on welded part when the system is pressurized due to incorrect welding procedure for the insulator. Hydraulic oil may leak and the warning light may illuminate when the crack progresses. In the worst case, the tractor may become unable to run and steer. The affected noise insulator should be replaced with the correct insulator.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
	F722VARIO S4	2016	1
	F724VARIO S4	2015	1