VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2403	DATE	November 11, 2016
MANUFACTURER	Hyundai Motor Company (Japanese importer :Hyundai Motor Japan Co., Ltd)		
DESCRIPTION OF DEFECT	Because storage condition of steel ball inside of the driver side electric power sheet switch is non-appropriate, corrosion by moisture occurs. By this corrosion, the contact point may contact without the operation of switch. As a result, driver side power sheet may operate freely because switch signal is sent to the power seat motor.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-TG27L	Grandeur	2007	4
ABA-TG33		2007~2008	25
		TOTAL	29