

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2407	DATE	November 28 th , 2016
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate design of the circuit board on the fuel pump control unit, dew condensation may cause a short circuit which leads to over current on FET. As a result, the fuel pump control unit might have an internal short when vehicle waking up from sleep mode/turning into sleep mode. In this case, the fuel pump will not work properly. When the deflection occurs, vehicle will be unable to start. In some rare cases, the fuel left in the fuel pipe will lead to engine stall during driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-XM12	MINI One	2015	223
DBA-XM15	MINI Cooper	2015	424
DBA-XM20	MINI Cooper S	2015	400
DBA-XMJCW	MINI JCW	2015	105
		TOTAL	1,152