

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3915	DATE	Nov.2, 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper design of the waterproof coupler between the brake switch harness and main harness, when coupler is being splashed with water, this water ingress into harness may cause corrosion inside the brake switch. And continued use in this condition, short circuit occurs in the internal circuit of the brake switch.</p> <p>In worst case, fuse melt open and headlamp, break lamp, tail lamp will not activate.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-GJ55D	GSR250	2012~2016	13,934
		TOTAL	13,934