

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3918	DATE	November 4,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the rear floor panel, the panels may have been welded at improper position due to inappropriate setting of the weld-gun orbit causing the weld-gun to interfere with the left rear portion of the rear floor panel. As a result, fuel may leak due to the breakage of the fuel system parts at the time of rear collision caused by insufficient strength of the left rear body structure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GF7W	「OUTLANDER」	2016	16
DBA-GF8W		2016	30
DLA-GG2W	「OUTLANDER PHEV」	2016	11
		TOTAL	57