

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3920	DATE	Nov. 2016
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>The road roller has the following issues.                  The choice of the power supply relay is inappropriate, due to a relay and an interlocking force of the relay holder are insufficient.                  Therefore the relay and the interlocking force of the relay holder become weak due to the vibrations during travelling and the supply of the power is quitted, and a fail-safe acts, and the engine output is limited temporarily.                  In the worst case, the relay is come off the relay holder, and the power is not supplied and an engine stops and might not be able to restart it.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-TBA	「ZC125M-5」	2014~2015	17
YDN-M12B3	「HM125H-3」	2014~2016	4
		TOTAL	21