

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3926	DATE	November 1,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the front wiper, the inside of the joint between the wiper motor and the wiper link may abnormally be worn in the event that water drops down through the gap between the front deck garnish and the windshield glass due to inappropriate water proof structure of the front deck. In the worst case, the joint between the wiper motor and the wiper link may separate causing the windshield wipers to stop operating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-CW4W	「OUTLANDER」	2010~2012	4,547
		2009~2010	2,910
DBA-CW5W		2005~2012	36,510
		2007~2010	25,294
DBA-CW6W		2009	1,868
		2007~2009	2,007
		2009	99
		TOTAL	73,235