

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3927	DATE	November 1,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the front wiper motor, the inside of the motor may corrode in the event that the water dropped down through the gap between the front deck garnish and the windshield glass intrudes into the inside the motor due to inappropriate water proof structure of the front deck. In the worst case, the wiper motor may stop operating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GA3W	「RVR」	2010～2012	18,273
DBA-GA4W		2011～2014	9,289
		TOTAL	27,562