

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3930	DATE	Nov. 25, 2016
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	<p>Since certain affected Subaru vehicles may have been produced with the engine water pump having an inadequate assembling clearance at the bearing, it may be broken and the water pump will malfunction.</p> <p>Under these circumstances, the timing belt will be damaged and if the vehicle was continuously driven, engine will stall and will possibly lead to no restart condition.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-BL5	LEGACY	2008~2009	1,553
DBA-BL9		2008~2009	34
DBA-BM9		2009~2010	5,071
CBA-BP5		2008~2009	2,996
CBA-BPH		2008~2009	906
DBA-BP9		2008~2009	28
DBA-BR9		2009~2010	7,224
CBA-YA5		EXIGA	2008~2010
DBA-YA4	2008~2010		6,550
DBA-YA5	2008~2010		7,076
CBA-SH5	FORESTER	2008~2010	6,400
CBA-SH9		2010	73
DBA-SH5		2008~2010	31,401
CBA-GVB	IMPREZA	2010	1,039
CBA-GVF		2010	978
DBA-GE2		2008~2010	2,539
DBA-GE3		2008~2010	2,216
CBA-GH8		2008~2010	2,856
CBA-GRB		2008~2010	4,348
CBA-GRF		2009~2010	3,510
DBA-GH2		2008~2011	21,481
DBA-GH3		2008~2010	8,450
		TOTAL	118,389