## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	3933	DATE	November 25, 2016		
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD				
DESCRIPTION OF	With regard to a hose connected to intercooler, the design of hose				
DEFECT	was improper, So its bend is sharp and some hoses have a winkle				
	at inner layer.				
	Therefore, the cause of the vibration of its engine, a crack might				
	happened that was started from the winkle, then if the crack was				
	extended, inner layer of the hose would be peeled off, and the				
	opening of intercooler would be clogged. In the worst case, it				
	would be increased the amount of a poisonous gas exhausted.				

ТҮРЕ	COMMERCIAL	MODEL YEAR		NUMBER OF
TIPE	NAME	RECALLED		VEHICLE
JDS-EE02	RK250-7	2008-2013		274 units
			TOTAL	274