

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3935	DATE	November 24,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the inflator for passenger side airbag, the propellant may be deteriorated by the repetitive changes of temperature and humidity due to improper performance in moisture absorption prevention of the propellant. As a result, the inflator body may rupture at the time of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-CV4W	「DELICA」	2009	215
DBA-CV5W		2007～2009	63,614
CBA-V83W	「PAJERO」	2006～2009	1,461
DBA-V83W		2009	27
CBA-V87W		2006～2009	805
ADC-V88W		2009	126
CBA-V93W		2006～2009	6,582
DBA-V93W		2009	116
CBA-V97W		2006～2009	2,896
ADC-V98W		2008～2009	1,471
DBA-CS2A	「LANCER」	2009	1,479
CBA-CS5AZ		2009	183
CBA-HA1W	「i」	2009～2011	2,848
DBA-HA1W		2009～2011	12,444
ZAA-HA3W	「i-MiEV」	2009～2011	6,213
		TOTAL	100,480