

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3936	DATE	November 24,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>In the gas-filled type spring for the tail gate, the end cap portion of the outer cylinder may rust due to inappropriate painting.</p> <p>If use continues at the condition, the end cap may be broken due to the swelling outer cylinder as the rust progresses. In the worst case, people around the tail gate may be injured by the ruptured outer cylinder at the time when the tail gate is opened.</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GA3W	「RVR」	2010～2012	18,273
DBA-GA4W		2011～2016	13,827
		TOTAL	32,100