

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3938	DATE	November 25, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to temperature cycling under humid condition. Therefore, during the airbag deployment, the container of inflator may be broken, components may be scattered, causing passengers to be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-ER3P	Mazda 「CX-7」	2006-2009	4,661
DBA-GHEFS	Mazda 「ATENZA」	2007-2009	542
DBA-GH5FS		2007-2009	4,704
CBA-GH5AS		2008-2009	326
DBA-GHEFP		2007-2009	2,881
DBA-GH5FP		2007-2009	2,154
CBA-GH5AP		2008-2009	190
DBA-GHEFW		2007-2009	1,078
DBA-GH5FW		2007-2009	5,627
CBA-GH5AW		2008-2009	765
			TOTAL