

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3942	DATE	Nov 30,2016
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On some wheel Crane engines, there are cases where the torque converter front covers are not of adequate strength due to improper front cover manufacturing leading to the cover cracking under hydraulic pressure during travel. With continued used of vehicle in this condition, the crack may progress to the point that the torque converter oil leak warning lamp lights up and, in the worst case, result in a loss of travel functions.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-T007	TADANO 「GR-250N-3」	2014-2016	687
UDS-T009	TADANO 「GR-160N-3」	2014-2016	136
UDS-EW07	KOBELCO 「RK160-7」	2015-2016	11
		TOTAL	834