

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3947	DATE	Nov.30 2016
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For the torque converter of the wheel cranes, found that the front cover was not strong enough due to improper manufacturing process, therefore, it might have a crack on it by hydraulic pressure while driving, then the crack might progress. When you keep using with this condition, you might have oil leakage from the converter which cause to illuminating of the warning light and might be unable to drive the vehicle at worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
UDS-KRC014	KRM - 20H	2014~2016	151	
UDS-KRC011	KR - 25H	2014~2016	845	
UDS-KRC015	KRM - 35H	2014~2016	117	
TOTAL			1113	