VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	395	1	DATE	November 30, 2016
MANUFACTURER	ISEKI & CO., LTD.			
DESCRIPTION OF DEFECT	For a agricultural tractor, because the shape of the pin whitch holds a rod connecting a clutch pedal and a clutch is inappropriate, the pin may be fall out by contacting branches when the tractor run onto pruned branches during the operation. Therefore in the worst case, a rod may come off, and a clutch may not be able to be disengaged.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
T226F	「Z15」	2015-2016		1263
			TOTAL	1263