VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3 9 5	2	DATE	November 30, 2016
MANUFACTURER	ISEKI & CO., LTD.			
DESCRIPTION OF DEFECT	For a agricultural tractor, because the heater hose of the air conditioner wiring is inappropriate, a return hose of the fuel may contact a heater hose, and be folded. Therefore, a return hose may crack by the vibration of the engine and the use in the condition may lead to progresses a crack, and fuel might leak out from the return hose.			
ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
T237F	「RTS25」	2016		62
T238F	「RTS23」	2016		10
			TOTAL	72