

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	外-2424	DATE	Dec. 27. 2016
MANUFACTURE	TEIKOKU SEN-I CO., Ltd.		
DESCRIPTION OF DEFECT	<p>Because the pitman arm in the steering device is not properly manufactured, cracking may occur at the bending portion of the arm. In the steering device, the pressure-regulating valve of the power steering is not properly adjusted. If use is continued in this state, these cracks will further progress and cause breakage, and in the worst case, it could lead to the situation where steering is impossible.</p> <p>For all the vehicles, the pitman arm is to be replaced to the countermeasure product and the pressure-regulating valve is to be properly adjusted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Rosenbauer	Panther 6x6	December 22, 2009 - September 29, 2015	VA96WC6899LRB1018 - VA96WJ685FLRB1002
		TOTAL	16 units