

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3931	DATE	Dec.1, 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the lack of heat resistant capacity of stator coil, the insulation material of wiring for the stator may be damaged by engine heat, and the short-circuit between wirings may occur.</p> <p>Continued use of Motorcycle with this condition, the generating current by the stator coil may be reduced and the insufficient charging to the battery may cause. In the worst case, it can lead to engine stalling during running and/or the engine may be impossible to restart.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-VP56A	V Strom	2013~2016	2,368
EBL-VK58A	GLADIUS	2010~2012	1,672
		TOTAL	4,040