

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3939	DATE	December 8, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the breather hose to release air inside fuel tank, due to improper hose material, some of breather hoses may deteriorate and crack under radiated heat influence of the exhaust system. As a result, in continuous use, the crack may develop leading to fuel leak. In the worst case, a fire may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-SKP2M	Mazda 「Bongo」	2012-2015	4,383
ABF-SKP2V		2012-2015	14,328
DBF-SLP2M		2016	812
DBF-SLP2V		2016	1,962
ABF-SKP2MN	NISSAN 「VANETTE」	2012-2015	6,349
ABF-SKP2VN		2012-2015	106
		Total	27,940