

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3956	Date	December 8 , 2016
Manufacturer	Mitsubishi Nichiyu Forklift Co., Ltd..		
Description of Defect	The battery cable which connects between the engine starter and the battery may be broken because the cable is too short to absorb the vibration from the engine and tension on the cable is hard enough to exceed fatigue strength of the material of the starter cable		

Model	Type	Commercial Name	Model Year Recalled	Number of Vehicles
Mitsubishi	YDM-F18D	Mitsubishi Forklift	2015/2016	8
Nichiyu	YDM-F14F		2015/2016	21
	YDM-KF18D		2015/2016	177
Total				206