

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3 9 5 7	DATE	December 22, 2016
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	<p>For a agricultural tractor, because the design of the rear wheel shaft is inappropriate, the flange of the shaft may be cracked by the load that is higher than design strength when the tractor work with the maximum weight implement in available.</p> <p>Therefore, the use in the condition may lead to progresses a crack, and in the worst case scenario, the shaft breaks, and might not be able to run.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-T152F	「TJW95」	2007	2
SC-T153F	「TJW105」	2006-2008	65
KDP-T165F	「TJW107」	2008-2014	47
EDR-T166F	「TJW117」	2008-2013	388
WDR-T214F	「TJW120」	2014-2015	46
WDR-T215F	「TJW108」	2015	11
		TOTAL	559