

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3963	DATE	Dec.21.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger air bag inflator of the subject vehicles, due to improper operation at the ignition booster filling process during suspension of the equipment, there is a possibility that the amount of filling could be small. In this condition, the airbag may not inflate properly during deployment.		

The affected parts shipped as repair parts, and could identify the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-NZE121G	[COROLLA FIELDER]	2005	1
CBA-NZE124G		2006	1
DBA-NZE121	[COROLLA RUNX]	2005	1
DBA-NZE141	[COROLLA AXIO]	2007	1
TA-MNH10W	[ALPHARD G]	2005	1
		TOTAL	5

The affected parts shipped as repair parts, and could not identify the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
Airbag module	04006-29153	2016	6
Airbag inflator	04006-04212	2016	8
Airbag inflator	04006-04458	2016	3
Airbag inflator	04006-66112	2016	16
		TOTAL	33