

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	2423	DATE	Jan.12, 2017
MANUFACTURER	SUZUKI MOTOR CORPORATION (Japanese Importer : SPK CORPORATION)		
DESCRIPTION OF DEFECT	Due to the lack of heat resistant capacity of stator coil, the insulation material of wiring for the stator may be damaged by engine heat, and the short-circuit between wirings may occur. Continued use of Motorcycle with this condition, the generating current by the stator coil may be reduced and the insufficient charging to the battery may cause. In the worst case, it can lead to engine stalling during running and/or the engine may be impossible to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C7111	V-Strom 650	2012~2015	195
		TOTAL	195