

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3944	DATE	January 27,2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>① In the engine starter, due to inappropriate programming of the engine control, the pinion gear of the starter motor may forcefully be fitted with the ring gear of the engine at the time of the shifting operation soon after the engine cranking start. As a result, the pinion gear may be broken by the impact and noise may occur when the engine is started. In the worst case, the engine may not be able to start.</p> <p>② In the engine control unit of the vehicle with the idling stop function, due to inappropriate programming of the engine control, the catalyst deterioration diagnosis may not work appropriately. As a result, the warning light may not turn on even when the catalyst is deteriorated.</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-B11W	「eK」	2013～2016	105,897
DBA-B11A	「eK SPACE」	2014～2016	48,488
DBA-B21W	「DAYZ」	2013～2016	261,445
DBA-B21A	「DAYZ ROOX」	2014～2016	191,599
		TOTAL	607,429