

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3972	DATE	January.19. 2017
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-GE6	「FIT」	2012	69,128	
DBA-GE7			7,751	
DBA-GE8			9,677	
DBA-GE9			1,345	
LA-GD1		2001	50	
LA-GD2			12	
DAA-GP1		「FREED」 「FREED SPIKE」	2012	55,830
DAA-GP4				8,640
DBA-GB3				53,938
DBA-GB4	5,132			
DAA-GP3	60,096			
DAA-GP2	60,961			
DBA-GG7	「FIT SHUTTLE」		5,565	
DBA-GG8			1,841	
LA-RN1			2000～2002	6,748
LA-RN2	1,294			
LA-RN3	8,720			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LA-RN4	「STREAM」	2001	16	
LA-ES1	「CIVIC FERIO」	2000	4,737	
LA-ES2			617	
LA-ES3			697	
DAA-ZE2	「INSIGHT」	2012	4,124	
DAA-ZE3	「INSIGHT EXCLUSIVE」		4,955	
DBA-RR1	「ELYSION」		1,160	
DBA-RR2	「ELYSION PRESTAGE」		149	
DBA-RR5	「ELYSION PRESTAGE」		272	
DBA-RR6			89	
DBA-CU1	「ACCORD」		817	
DBA-CU2			312	
DBA-CW1	「ACCORD TOURER」		529	
DBA-CW2			484	
DBA-CP3	「INSPIRE」		577	
DBA-KB2	「LEGEND」		227	
ZAA-ZA2	「FIT EV」		36	
ZBA-ZC3	「FCX CLARITY」		1	
			TOTAL	376,527