

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 9 7 7	DATE	Jan.27.2017
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the pump of the ABS actuator, due to an inappropriate adjustment of assembly facility, the seal in the pump was damaged when it was installed. Therefore, the discharge pressure of the brake fluid may be insufficient when the ABS is operated, in an extreme case, the ABS function cannot be operated and the running stability might be spoiled.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-GFC27	SERENA	2016	7,789
DAA-GFNC27			1,321
DAA-GC27			2,414
DAA-GNC27			815
DBA-C27			463
		TOTAL	12,802