

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3983	DATE	Feb. 2 2017
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty route buses, the material of a rubber part used in the starter is improper and the margin for wear of the flywheel ring gear is insufficient. Because of these causes, if the engine is started frequently by the idling stop and start system, the ring gear may wear prematurely. If the vehicle continues to be used in this condition, the starter gear will start to slip and, in the worst case, it will become impossible to start the engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-MP35FM	「FUSO AERO STAR」	2015	1
QKG-FK62FZ		2015	1
		TOTAL	2