

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3991	DATE	Feb 9 , 2017
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>There are gear shift rear shafts of which strength is insufficient on Manual transmission model.</p> <p>On repeating shift operation, crack occurs on gear shift rear shaft. If it is used continuously, the shaft would break off, in the worst case, shift operation could become impossible and it becomes impossible to drive.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-TDA4W	ESCUDO	2008~2013	1,116
		TOTAL	1,116