

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3998	DATE	Feb. 23, 2017
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to an inappropriate program of an engine control unit, when intake air temperature is high, ignition timing, fuel injection and/or boost pressure may not be controlled properly and abnormal combustion may occur. If it occurs, a connecting rod may break with abnormal high pressure in a cylinder. In the worst case, a cylinder block is damaged, engine oil leaks and it may be resulting fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「LEVORG」	2014~2016	64,683
		TOTAL	64,683